Re: usr sportster won't answer call

Source: http://www.derkeiler.com/Newsgroups/comp.os.linux.security/2003−02/0279.html

---

From: Clifford Kite (*kite@see.signature.id*)
Date: 02/09/03

```
From: Clifford Kite <kite@see.signature.id>
Date: Sun, 09 Feb 2003 12:53:19 −0000
```

In comp.os.linux.misc Laplace <Laplace@tranforms.org> wrote:

> *usr sportster won't answer call at root account minicom*

> *I entered ats0=1 and at&w0*
> *then in window 98 se I dial in ok.*

> *but when it is reboot .*
> *at&w0 is not writing into the current profile.*

Do you have ATZ[0|1] for initialization on reboot? The factory profile(s)
are not changed.

> *modem won't answer at all.*
> *do u know why?*

> *is there my "at&w0" wrong? it is not writing the "ats0=1" into the modem*
> *profile.*

If using ATZ doesn't work, put the ATS0=1 into the modem initialization
string. My modem recognizes the AT&W0 but doesn't store a the profile
in non−volatile memory. The modem is not a USR but the command is
accepted without error, very likely for "compatibility" with the old
Hayes standard.

> *Laplace.*

Good ancestry.

[Followups directed to comp.os.linux.hardware, comp.os.linux.misc only.]

```
−−
Clifford Kite                Email: "echo xvgr_yvahk−ccc@ri1.arg|rot13"
PPP−Q&A links, downloads:    http://users3.ev1.net/~ckite/public_html/
/* In my book, the first poster to resort to personal abuse in a Usenet
   debate loses by default.  −  Rod Smith */
```